

## **TR3080 Remote Control Drone with Headless Mode**

Before proceeding, please ensure that the Drone has been fully charged. This is achieved by plugging the USB charger to a USB port and the drone. Charging time is approximately 45 minutes.

The remote controller requires 4 x AA Batteries. Please do not mix different types of batteries.

### **Quick Start Guide:**

1. Turn the switch to ON position on the drone (located on the bottom of drones body)
2. Turn on the remote controller by pressing the On/Off switch located on the center.
3. After two seconds, the drone is paired and ready to fly.